



429823

Ref. 62

**Range, Lance**

**From:** Zintak.Leonard@epamail.epa.gov  
**Sent:** Wednesday, November 16, 2011 3:32 PM  
**To:** Range, Lance  
**Subject:** Re:

Lance, We have not done any major work on the Horseshoe Area yet other than surveying and some geotechnical work. The area drains to the southwest into the wetlands area upstream of Smallpox Creek. The drainage channel at the southwest part of the Horseshoe Area has eroded considerably since the big 13.5" flood this summer. There are no pipes in this area. Does that answer your question? Thanks

---

Len Zintak  
On-Scene Coordinator  
U.S. EPA Region 5  
Chicago, IL  
(312) 886-4246 Office  
(312) 353-9176 FAX  
(312) 353-2318 24-hr Emergency  
[zintak.leonard@epa.gov](mailto:zintak.leonard@epa.gov)

-----"Range, Lance" <[Lance.Range@Illinois.gov](mailto:Lance.Range@Illinois.gov)> wrote: -----

To: LEONARD ZINTAK/R5/USEPA/US@EPA  
From: "Range, Lance" <[Lance.Range@Illinois.gov](mailto:Lance.Range@Illinois.gov)>  
Date: 11/15/2011 09:14AM  
Subject: (Untitled)

Hi Leonard

I am currently working on the doc record for Bautsch

It has been awhile since I have been up there, but could you tell me if the overflow pipe from the horseshoe shaped impoundment has been reinstalled and if it still drains to the south of the dam?

Thanks, much appreciated.

Lance L. Range

Illinois Environmental Protection Agency

1021 N. Grand Avenue East

Springfield, IL 62794

217-524-1661

[lance.range@illinois.gov](mailto:lance.range@illinois.gov)